



Shielding Gas Recommendations for Arc Welding

Material	TIG	Flux Core with Gas	Transfer Mode	MIG	Metal Core ¹
Carbon Steel	100% Ar	100% CO ₂ or 75%Ar/20%CO ₂	Short Circuit	100% CO ₂ or 75%Ar/25%CO ₂	100% CO ₂ or 75%Ar/25%CO ₂
			Spray / Pulse	90%Ar/10%CO ₂ ³	90%Ar/10%CO ₂ ³
Low Alloy Steel	100% Ar	100% CO ₂ or 75%Ar/20%CO ₂	Short Circuit	75%Ar/25%CO ₂ ⁴	75%Ar/25%CO ₂ ⁴
			Spray / Pulse	98%Ar/2%CO ₂ ⁵	98%Ar/2%CO ₂ ⁵
Stainless Steel	100% Ar	100% CO ₂ or 75%Ar/20%CO ₂	Short Circuit	90%He/7.5%Ar/2.5%CO ₂	N/A
			Spray / Pulse	98%Ar/2%CO ₂ ⁶	98%Ar/2%CO ₂ ⁶
Aluminum	100% Ar ²	N/A	Spray / Pulse	100% Ar ²	N/A
Nickel Alloys	100% Ar	N/A	Short Circuit	100% Ar	N/A
			Spray / Pulse	100%Ar or 75%Ar/25%He	
Copper Alloys	100% Ar	N/A	Spray / Pulse	100%Ar or 75%Ar/25%He	N/A

Notes

¹ It is possible to operate Metal Core in short circuit transfer. However, performance is poor. They operate best with spray or pulse spray arc mode.

² On thicker plate, 100% He or Ar/He mix may be used for more radiated heat into the plate.

³ Other Ar/O₂ blends can be use with a minimum of 82% Ar. 80%Ar/20CO₂ is sometimes used.

⁴ 100% CO₂ may be used.

⁵ 95%Ar/5%CO₂ and 90%Ar/10%CO₂ and other gases mixes can be used.

⁶ 90%Ar/2%CO₂ may be used.